

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 0017 Mossdale

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 French Camp Slough	Left	1.76	10/15/2015 10/15/2015	Richard Willoughby

LM Start	0.00	Rating **	A	Issue No.	1	
LM End	0.00	Issue Type +	Ma	Location *	N/A	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Operations & Maintenance Manuals				o	
					o	
DWR ID	DWR_RD0017_01_s _ 2013_1					
Action/Comments						
Inspector Comments: LMA has a copy of the manual on file.						

No Photos

LM Start	0.00	Rating **	A	Issue No.	2		
LM End	0.00	Issue Type +	Ma	Location *	N/A		
Category	Earthen Levee			GPS Latitude/Longitude			
				Start		End	
Item	Emergency Supplies & Equipment				°		°
					°		°
DWR ID	DWR_RD0017_01_s _ 2013_2						
Action/Comments							
Inspector Comments: LMA has adequate flood fight supplies.							

No Photos

LM Start	0.00	Rating **	A	Issue No.	3
LM End	0.00	Issue Type +	Ma	Location *	N/A
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Flood Preparedness & Training				°
					°
DWR ID	DWR_RD0017_01_s _ 2013_3				
Action/Comments					
Inspector Comments: District staff are involved in yearly training sponsored by DWR.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 0017 Mossdale

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 San Joaquin River	Right	14.27	10/15/2015 10/15/2015	Richard Willoughby

LM Start	1.08	Rating **	U	Issue No.	2
LM End	1.08	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR Erosion Survey			37.902530 °	37.902530 °
				-121.325690 °	-121.325690 °
DWR ID					
Action/Comments					
Inspector Comments: 06/24/2015: No significant change observed. 6/19/2014: No significant change observed. 08/13/2013: No significant change at this site. 08/07/2012: The erosion is nearly vertical, and has developed upward to halfway of the levee slope. The protecting concrete blocks have been washed away. Animal activities are visible. [2015 Site ID:RD0017U02RM44.32]					

Photo 1 of 2 : SJR2015_RD0017U02RM44.32_1.jpg



Front view of the erosion site. Note the concrete blocks and vegetation.

LM Start	1.08	Rating **	U	Issue No.	2 (cont)
LM End	1.08	Issue Type +	Ma	Location *	WS

Photo 2 of 2 : SJR2015_RD0017U02RM44.32_3.jpg



Close view of the erosion.

LM Start	1.16	Rating **	C	Issue No.	78
LM End	1.16	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			37.901318 °	37.901318 °
				-121.325522 °	-121.325522 °
DWR ID	DWR_RD0017_02_s_2015_78				
Action/Comments					
Schedule repair of erosion site prior to the next inspection.					
Inspector Comments: Sink hole (4' x 18" x 5')next to pipe.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	---	--	---	--	--	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 0017 Mossdale

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 San Joaquin River	Right	14.27	10/15/2015 10/15/2015	Richard Willoughby

LM Start	1.29	Rating **	C	Issue No.	3
LM End	1.29	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR Erosion Survey			37.899510 °	37.899510 °
				-121.326030 °	-121.326030 °
DWR ID					
Action/Comments					
Inspector Comments: 06/24/2015: No significant change observed. 06/19/2014: The erosion has been repaired. A minor erosion is still visible near the tree. 08/13/2013: A mid-size tree is present immediately upstream of the erosion, which could block the view of the site. Some debris is visible. [2015 Site ID:RD0017U02RM44.52]					

No Photos

LM Start	2.66	Rating **	C	Issue No.	5
LM End	2.66	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR Erosion Survey			37.881020 °	37.881020 °
				-121.332260 °	-121.332260 °
DWR ID					
Action/Comments					
Inspector Comments: 06/24/2015: Erosion has been repaired. 6/19/2014: The erosion was probably caused by the irrigation pipe found at the site. [2015 Site ID:RD0017U02RM45.94]					

No Photos

LM Start	2.67	Rating **	M	Issue No.	6
LM End	2.69	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR Erosion Survey			37.880710 °	37.880710 °
				-121.332200 °	-121.332200 °
DWR ID					
Action/Comments					
Inspector Comments: 06/24/2015: Levee has been cut at the mid slope and a temporary step has been made for unknow purpose. More erosion has been found at the site. 6/19/2014: The erosion is in the river bank which has an estimated 10-ft wide berm. [2015 Site ID:RD0017U02RM45.95]					

Photo 1 of 2 : SJR2015_RD0017U02RM45.95_1.JPG



Front view of the erosion site. Note the new cut at the middle levee slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 0017 Mossdale

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 San Joaquin River	Right	14.27	10/15/2015 10/15/2015	Richard Willoughby

LM Start	2.67	Rating **	M	Issue No.	6 (cont)
LM End	2.69	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR Erosion Survey			37.880710 °	37.880710 °
				-121.332200 °	-121.332200 °
DWR ID					
Action/Comments					
Inspector Comments: 06/24/2015: Levee has been cut at the mid slope and a temporary step has been made for unknow purpose. More erosion has been found at the site. 6/19/2014: The erosion is in the river bank which has an estimated 10-ft wide berm. [2015 Site ID:RD0017U02RM45.95]					

Photo 2 of 2 : SJR2015_RD0017U02RM45.95_4.JPG



Close view of the erosion.

LM Start	2.78	Rating **	C	Issue No.	7
LM End	2.79	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR Erosion Survey			37.879293 °	37.879293 °
				-121.332518 °	-121.332518 °
DWR ID					
Action/Comments					
Inspector Comments: 06/24/2015: No significant change observed. 06/19/2014: The erosion has been repaired. 08/13/2013: Found during boat survey. There is vegetation at the site. [2015 Site ID:RD0017U02RM46.03]					

No Photos

LM Start	2.82	Rating **	M	Issue No.	8
LM End	2.82	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR Erosion Survey			37.878660 °	37.878660 °
				-121.332400 °	-121.332400 °
DWR ID					
Action/Comments					
Inspector Comments: 06/24/2015: No significant change observed. 06/19/2014: A pocket erosion was found during the boat survey. [2015 Site ID:RD0017U02RM46.1]					

Photo 1 of 2 : SJR2015_RD0017U02RM46.10_1.JPG



Front view of the erosion.

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 0017 Mossdale

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 San Joaquin River	Right	14.27	10/15/2015 10/15/2015	Richard Willoughby

LM Start	2.82	Rating **	M	Issue No.	8 (cont)	
LM End	2.82	Issue Type +	Ma	Location *	WS	
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR Erosion Survey			37.878660 °		37.878660 °
				-121.332400 °		-121.332400 °
DWR ID						
Action/Comments						
Inspector Comments: 06/24/2015: No significant change observed. 06/19/2014: A pocket erosion was found during the boat survey. [2015 Site ID:RD0017U02RM46.1]						



Close view of the erosion. The slope protection is poor.

LM Start	3.63	Rating **	M	Issue No.	10
LM End	3.63	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR Erosion Survey			37.868500 °	37.868500 °
				-121.327670 °	-121.327670 °
DWR ID					
Action/Comments					
Inspector Comments: 06/24/2015: No significant change observed. 06/19/2014: The erosion is near a large tree and probably has been caused by the irrigation pipe on the site. [2015 Site ID:RD0017U02RM46.89]					



Front view of the erosion. Note the tree and the irrigation pipe.

LM Start	3.63	Rating **	M	Issue No.	10 (cont)
LM End	3.63	Issue Type +	Ma	Location *	WS



Close view of the erosion.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 0017 Mossdale

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 San Joaquin River	Right	14.27	10/15/2015 10/15/2015	Richard Willoughby

LM Start	5.52	Rating **	A/W	Issue No.	76
LM End	5.52	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.850118 °	37.850118 °
				-121.320188 °	-121.320188 °
DWR ID	DWR_RD0017_02_s _ 2012_76				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows. Inspector Comments: Rodent holes has been backfilled, but should be monitored.					

No Photos

LM Start	6.74	Rating **	A/W	Issue No.	79
LM End	6.74	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.838810 °	37.838810 °
				-121.316600 °	-121.316600 °
DWR ID	DWR_RD0017_02_s _ 2015_79				
Action/Comments					
Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comments: Remove cactus on waterward slope.					

No Photos

LM Start	7.19	Rating **	A/W	Issue No.	18
LM End	7.19	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			37.833162 °	37.833162 °
				-121.312715 °	-121.312715 °
DWR ID	DWR_RD0017_02_s _ 2013_18				
Action/Comments					
Trim trees to at least five feet above ground level.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 0017 Mossdale

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 San Joaquin River	Right	14.27	10/15/2015 10/15/2015	Richard Willoughby

LM Start	7.42	Rating **	M	Issue No.	4
LM End	7.42	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			37.830350 °	37.830350
				-121.310880 °	-121.310880
DWR ID	DWR_RD0017_02_s _ 2012_4				
Action/Comments					
Trim trees to at least five feet above ground level.					

No Photos

LM Start	7.58	Rating **	M	Issue No.	25
LM End	7.60	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.828095 °	37.827920 °
				-121.309945 °	-121.309847 °
DWR ID	DWR_RD0017_02_s _ 2012_25				
Action/Comments					
Elderberries are blocking visibility and flood fight capability.					

Photo 1 of 1 : FA_2015_RD0017_304_25_20150914_00007.jpg



Elderberry blocking view of landside slope and toe.

LM Start	9.28	Rating **	U	Issue No.	9
LM End	9.28	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.815243 °	37.815243 °
				-121.317470 °	-121.317470 °
DWR ID	DWR_RD0017_02_s _ 2012_9				
Action/Comments					
Trees / Woody Vegetation					
Inspector Comments: Bamboo located at landward toe.					

Photo 1 of 1 : FA_2015_RD0017_304_9_20150914_00005.jpg



Looking east at bamboo at landward toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2015

Reclamation District No. 0017 Mossdale

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 San Joaquin River	Right	14.27	10/15/2015 10/15/2015	Richard Willoughby

LM Start	10.64	Rating **	M	Issue No.	80
LM End	10.64	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.805787 °	37.805787 °
				-121.322022 °	-121.322022 °
DWR ID	DWR_RD0017_02_s _ 2015_80				
Action/Comments					
Elderberries are blocking visibility and flood fight capability.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---